







# Explanation

- SB-9  Soil Sample Location
-  Repaving Area
-  Rail Spur
-  Chain Link Fence



**PES Environmental, Inc.**  
Engineering & Environmental Services

**Repaving  
Soil Sample Locations**  
Univar USA Inc.  
Portland, Oregon

FIGURE  
**1**

816.001.02.003	81600102003_soilchar		6/07
JOB NUMBER	DRAWING NUMBER	REVIEWED BY	DATE